





September 2022

BOAT-LANDING TRANSFERS: A CRITICAL OPERATION!

During a passenger transfer, the weakened SEWOP-type (Self Elevating Work Over Platform) Boat-landing structure fell into the water. Thanks to the good reaction of the crew, the incident did not cause any injury or damage.

- Report all non-conformities observed at the Boat-landing to the client!
- Reminder: the camera at the Boat-landing must be operational on 100% of Surfers with data record and storage capacity at least 15 days, and videos shall be available for investigation.

THE SAFETY POST IS BASED ON REAL EVENTS - PLEASE PRINT, POST AND DISCUSS THIS ISSUE!



LIFE SAVING RULES

DO:

DON'T:

• Do not hesitate to apply the stop work authority when a hazardous situation is identified.



• Perform operations when Boat-landing is in poor conditions.