



WATCH YOUR HANDS!

Following the replacement of the davit winch, the crew undertook to test the device. The chief engineer in charge of the operation wanted to shove off the Fast Rescue Craft (FRC) and lower it by 1 or 2m but following an insufficient preparation to work and a lack of supervision, all will not occur as planned...



THE SAFETY POST IS BASED ON REAL EVENTS - PLEASE PRINT, POST AND DISCUSS THIS ISSUE!



- > **UNCLEAR TASK DESCRIPTION**
- > **LACK OF EXCHANGE WITHIN TEAM**
- > **LACK OF SUPERVISION**
- > **IGNORANCE OF RISK**



- > **INAPPROPRIATE ROPE HANDLING**
- > **WRONG GLOVES TYPE**



LIFE SAVING RULES

DO:

- During TBT, person in charge shall ensure active participation of the crew, knowledge of the hazard and understanding of the task
- Have a specific FRC launching and testing procedure
- Know rope handling technics
- Wear appropriate gloves to ropes handling (impact gloves)

